



Multiple Luna system ( +  + ...)


①




①




②




③




④




①




②




Single Luna system ()


①




①




②





③



④



Annual service





Recommend



Würth

Contact spray oxidation solvent
Art.-no. 089360

Troubleshooting

Description:	Error:	Solution:
<p>Moves in steps.</p> 	<p>Luna battery low.</p>	<p>Charge Luna.</p>
<p>No rotation.</p> 	<p>Missing power from Luna.</p>	<ol style="list-style-type: none"> 1. Follow annual service. 2. Replace conductor wheels.

Manufacturer:
WinnCare Nordic ApS
Taarnborgvej 12C
4220 Korsoer
Denmark
www.winnCare.com

Distributor/service:

Date: 25-04-2022
Version: 1
UM-910-05007EN